


# Wiring Diagram

For full diagram refer to the X409-WRA-JL installation manual.



---

## Mounting Location

---

The KTX-F200INT has 30” of cable so it can be routed behind the glovebox. It is important to do this so it can disappate heat properly.

